

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
NY
60-IRU
4A -

Addendum to:

Old Croton Aqueduct
Jewels Brook Culvert
Spanning Station Rd.
Irvington
Westchester County
New York

HAER NY-114

NY-114-1 Photocopied October 1976, from F.B. Tower,
 Illustrations of the Croton Aqueduct, New York:
 Wiley and Putnam, 1843.
 CROTON AQUEDUCT AT JEWELS BROOK, PLATE XVI, PAGE 105.

Jack Boucher, photographer, 1978

NY-114-2 AERIAL VIEW OF JEWELS BROOK CULVERT. LOOKING EAST.

NY-114-3 AERIAL VIEW LOOKING EAST, SHOWING JEWELS BROOK ON
 LEFT AND STATION RD. ON RIGHT.

NY-114-4 AERIAL VIEW LOOKING SOUTH SHOWING AQUEDUCT RIGHT-
 OF-WAY AT JEWELS BROOK.

NY-114-5 AERIAL VIEW LOOKING WEST AT JEWELS BROOK. CULVERT
 IS OBSCURED BY TREES.

NY-114-6 GENERAL VIEW AT JEWELS BROOK SHOWING ROADWAY ARCH
 (LEFT) AND ARCH SPANNING BROOK (RIGHT).

NY-114-7 GENERAL VIEW SHOWING JEWELS BROOK AND THE CULVERT
 IT PASSES THROUGH.

NY-114-8 GENERAL VIEW SHOWING ARCH THAT SPANS STATION RD.